

## Project:

Service Reservoir

#### Location:

Warwick

### Owner/s:

Severn Trent

## Applicator/Contractor:

Stonbury

### Market sector:

Clean Water Industry

### Products used & amounts:

MasterSeal 586 - 1200m<sup>2</sup> MasterSeal 930 bandage with MasterSeal 933 adhesive - 120 linear metres

### Sales Contact:

Darren.priddle@mbcc-group.com

### **Technical Contact:**

christopher.gallivan@mbcc-group.com

# Service Reservoir, Warwick

Waterproofing of joints and concrete protection



Our reference in Warwick (United Kingdom): Service Reservoir

# The background

This underground service reservoir lies in the heart of the Warwickshire countryside. The concrete structure required maintenance to the joints and re-levelling of the internal concrete surface.

## The challenge

The contract required the removal of all existing contamination back to sound concrete.

A moisture tolerant adhesive and joint bandage was needed that could offer a fast return to service time to seal the leaking joints.

The contract required a cementitious levelling mortar with a fast return to service time to reprofile the concrete surface.

All materials had to be Regulation 31 approved for use in contact with potable water.

### **Head Office:**

Master Builders Solutions UK Ltd Swinton Hall Road Swinton Manchester M27 4EU, United Kingdom Master Builders Solutions UK Ltd 19 Broad Ground Road, Lakeside, Redditch, Worcestershire, B98 8YP, United Kingdom

A brand of **MBCC** GROUP

# Service Reservoir, Warwick

# Waterproofing of joints and concrete protection





Our reference in Warwick (United Kingdom): Service Reservoir

## **Our solution**

The concrete surface was treated with high pressure water to remove all contaminants. MasterSeal 930 bandage was applied onto MasterSeal 933 moisture tolerant adhesive to seal the vertical and horizontal joints. MasterSeal 586 was applied in one layer of 3mm to re-profile the concrete walls.

# The customer's benefit

- MasterSeal 933 adhesive can be applied to surface-dry concrete, avoiding the extra cost of heating to dry the concrete. The fast return to service of 10 days at 7°C enabled the reservoir to be recommissioned on schedule.
- MasterSeal 586 applied at 3mm provides a smooth surface to reconstitute the original concrete finish. The rapid return to service time of three days at 3°C ensured there was no delay between completing the re-profiling works and recommissioning the reservoir.
- MasterSeal 930 bandage, MasterSeal 933 adhesive and MasterSeal 586 levelling mortar are all Regulation 31 approved for use in contact with potable water.

### Projects facts at a glance

- Potable water reservoir servicing Warwick
- Preparation of the concrete surfaces
- Regulation 31 approved joint bandage and levelling mortar applied

### **Master Builders Solutions by MBCC Group**

The Master Builders Solutions brand expresses MBCC Group's expertise in providing customized chemical solutions for new construction, maintenance, repair and restoration of structures.

Master Builders Solutions is built on the experience gained from more than a century in the construction industry. At the core of the Master Builders Solutions brand is the combined know-how and experience of a global community of construction experts, who connect with you to solve all of your construction challenges.

Further information is available at: www.master-builders-solutions.com