## **Technical Bulletin**



## **Cracks in Cement Plaster Stucco**

In this bulletin we discuss some common causes of cracks in cement plaster stucco as well as recommended measures that can limit the extent of cracking in cement plaster stucco wall systems.

Northwest Wall and Ceiling Bureau, a leading resource for plastering information, clearly states: "Cement plaster stucco is a Portland cement product, and, as with all Portland cement products it is susceptible to the occasional crack no matter how good the installation."

Several conditions can lead to cracking. Thermal expansion and contraction generates stresses in cement plaster stucco. Proper placement and installation of control joints can help alleviate the effects of these stresses. Other stresses on the stucco wall can result from excessive loading on walls, impact, vibration, building settlement and movement. In wood-framed construction, additional stresses result when framing members twist, warp and bow within the wall assembly while drying. Such stresses exert themselves at locations in the stucco where strength and resistance are insufficient to prevent a break in the stucco.


The most common cracks in cement plaster stucco form at the corners of doors, windows and other penetrations. According to the Stucco Manufacturers Association, "Minor cracking at the corners of doors and windows and other stress points is reasonable and should be anticipated."

In addition, "shrinkage cracks may develop as the excess water evaporates from the drying cement mix. Shrinkage cracks can occur very early on and cannot be seen after the finish coat is applied. Hairline or egg shell cracking or checking in the finish coat is also the result of rapid drying, most commonly occurring on hot, windy days." It is important to understand that cracks of this kind are not indications of substandard plasterwork or materials, and should not lead to assumptions that the stucco will not perform properly.

Although it is beyond the scope of this Technical Bulletin to cover all potential causes of cement plaster stucco cracks, the following are in addition to those provided above and some of the more common:

- Improper location or lack of properly installed expansion/control joints.
- Improper spacing/gapping of wood based sheathings as required by the APA (American Plywood Association).
- Improper loading of the roof and structure prior to the lath installation
- Installation and/or loading of interior drywall after the cement plaster stucco installation.
- Failure to properly moist cure the stucco for the first 48 hrs after application as required.
- Installation of the lath or plaster base outside of required ASTM C1063 guidelines.
- Failure of the wall to meet the required deflection criteria; maximum of L/360.
- Improper mix ratios of the cement plaster stucco mix; i.e. cement rich or excessive sand in mix.
- Application of the finish coat before the base coat has properly cured.

Master Builders Solutions Stucco Resurfacing System is designed to help reduce the appliance of hairline cracks in Stucco Systems. This method of installation involves the application of a fiberglass reinforcing mesh embedded in an acrylic polymer modified cement base coat over the entire, properly cured cement brown coat. For additional information, reference Technical Bulletin "Procedures for Repairing Stucco."



Master Builders Solutions manufacturers a variety of high quality, cement plaster stucco products which can provide long lasting exterior finish options for a wide variety of applications. It is important to understand that MBS does not warrant against cracking in cement plaster stucco. Should questions arise regarding the presence of cracks in cement plaster stucco, MBS would recommend the involvement of a qualified engineering firm for further investigation.

For additional information regarding this or other stucco-related topics, Master Builders Solutions Wall Systems recommends the following resources: Portland Cement Association (www.cement.org), Northwest Wall and Ceiling Bureau (www.nwcb.org) and the Stucco Manufacturers Association (www.stuccomfgassoc.com).

## LIMITED WARRANTY NOTICE

Master Builders Solutions Construction Systems US, LLC ("Master Builders") warrants this product to be free from manufacturing defects and to meet the technical properties on the current Technical Data Guide, if used as directed within shelf life. Satisfactory results depend not only on quality products but also upon many factors beyond our control. MASTER BUILDERS MAKES NO OTHER WARRANTY OR GUARANTEE, EXPRESS OR IMPLIED, INCLUDING WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE WITH RESPECT TO ITS PRODUCTS. The sole and exclusive remedy of Purchaser for any claim concerning this product, including but not limited to, claims alleging breach of warranty, negligence, strict liability or otherwise, is shipment to purchaser of product equal to the amount of product that fails to meet this warranty or refund of the original purchase price of product that fails to meet this warranty, at the sole option of Master Builders. Any claims concerning this product must be received in writing within one (1) year from the date of shipment and any claims not presented within that period are waived by Purchaser. MASTER BUILDERS WILL NOT BE RESPONSIBLE FOR ANY SPECIAL, INCIDENTAL, CONSEQUENTIAL (INCLUDING LOST PROFITS) OR PUNITIVE DAMAGES OF ANY KIND.

Purchaser must determine the suitability of the products for the intended use and assumes all risks and liabilities in connection therewith. This information and all further technical advice are based on Master Builders' present knowledge and experience. However, Master Builders assumes no liability for providing such information and advice including the extent to which such information and advice may relate to existing third party intellectual property rights, especially patent rights, nor shall any legal relationship be created by or arise from the provision of such information and advice. Master Builders reserves the right to make any changes according to technological progress or further developments. The Purchaser of the Product(s) must test the product(s) for suitability for the intended application and purpose before proceeding with a full application of the product(s). Performance of the product described herein should be verified by testing and carried out by qualified experts.

FOR PROFESSIONAL USE ONLY. NOT FOR SALE TO OR USE BY THE GENERAL PUBLIC.

For the most current version of this literature, please visit our website at master-builders-solutions.com/en-us.